


HOBO ??????????

[illegible]

HOBO??????HOBOWare????CD????USB????????????????????????????



Supported Measurements

Features

- ## Contact Us

- Email sales@onsetcomp.com
- Call 1-508-759-9500
- In U.S. toll free 1-800-564-4377
- Fax 1-508-759-9100

- Contact Product Support www.onsetcomp.com/support/contact
- Call 1-508-759-9500
- In U.S. toll free 1-877-564-4377

Onset Computer Corporation
470 MacArthur Boulevard
Bourne, MA 02532

HOBO ?????????? (U10-003) Specifications

????
 ???-20°C?70°C?-4°F?158°F?
 ?????RH??25%?95% RH
 ??
~~PI60A~~not found or type unknown
 ???0°C?50°C??±0.53°C?32°F?122°F??±0.95°F????A
 ?????RH??15°C?45°C?59°F?113°F????25%?85%??±3.5%???B?5°C?55°C?41°F?131°F????25%?95%??±5%???B
 ???
 ???25°C??0.14°C?77°F??0.25°F????A
 ?????RH??25°C?30% RH??0.07%
 ???
 1??18??????
 ??
 ???0.1°C/??0.2°F/?
 ?????RH?????1%/?
~~PI60B~~not found or type unknown
 ?1 m/s?2.2 mph????????
 ???????90%?10??
 ?????RH??????90%?6??
 ?????25°C?77°F????±1?/????C
 ?????
 ???-20°C?70°C?-4°F?158°F??0?95% RH????
 ????????????1?
~~PI60B~~RHfound or type unknown
 ???64K???52,000?10????
 ???26??0.82??
 ???45×60×20???1.8×2.38×0.77???
 CE???????????EU???????